


Tevatron Magnet Studies

Pierre Bauer


- •b2 drift and snapback in Tevatron dipoles
- drift of a1 in Tevatron dipoles
- drift of b0 in Tevatron dipoles
- •(geometric) skew quad in Tevatron dipoles (& change thereof on ramp)
- other activities

Magnetic Measurements at the Magnet Test Facility






Magnetic Measurement Example



Dynamic b2 in Tevatron Dipoles



b2 D&SB after 30 min injection porch for a standard pre-cycle in 5 Tevatron dipoles (note change of scale on abscissa)


time-structure of SB

drift amplitude

magnet-to-magnet spread in dynamic effects




Beam Based Measurements - Dynamic b2



Average Tevatron dipole b2 SB after 20 & 120 min injection porch, derived from measured beam chromaticity (dashed: b2 compensation)




Effect of Pre-Cycle Flat-Top Duration on Dynamic b2



b2 drift amplitude in 5 magnets

SB in 1220 for diff. FT durations




6



Magnetic Measurement: Dynamic a1/b1

Possible magnet borne causes of tune/coupling drift:

- •0.1 units of a1, b1 drift in all dipoles
- •2 units of main field drift in quad magnets




® Progress on characterization of a1 drift...

a1 drift in Tevatron dipole 269 during the injection porch following a standard pre-cycle



Magnetic Measurements: Main Field Drift

First evidence of main field drift in Tevatron dipoles:




B0 drift at injection in 4 dipoles after standard pre-cycle.



Magnetic Measurements: a1 Issue

a1 ® strong coupling, possibly caused by dropping of coil in yoke that occurred during first years of Tevatron operation;

Magnet	D in cold lift 82- 02 (mils)	D in a1 82-02 (units)
TB0269	+8.5 / +7.0	+1*
TC1220	+4.1 / +6.0	+1*
TB0834	+11.3 / +11	+3*
TC0483	+4.2 / +6.2	+0.4*




^{* 82} and 02/03 measurements were performed with different rotating coil assemblies in different positions of the magnet body. Therefore data are suggestive but conclusions cannot be drawn yet ® variation of a1 measurements along magnet length, change in b1 appeared also!



Longitudinal variations of a1

Possible causes:


- Variations of coil position with respect to yoke
- Coil shape variations, especially between lower and upper pole



Plot of geometric a1 along axis of magnet 0525.



Magnetic Measurement: Da1 During Ramp



a1 vs current in TC1220, measured in 82 & 03.

average a1 vs current of all dipoles installed (archive data).



Other Activities:

Re-shimming – Demonstration experiments:

•3 dipole magnets were re-shimmed and a1 measured along the length – before/after re-shimming® procedures developed for re-shimming in tunnel,

Re-rolling experiments:

•Rolling of dipole in string to verify if roll correction can be performed in tunnel without damaging the magnet vacuum. Also tested: if coil rolls back with the yoke.....experiment currently in progress

Towards on-line Tevatron field diagnostics:

•hardware development launched including design of fast DSP/ADC based system, long warm-bore and new probes



Achievements - Summary

•improved b2 snapback fit proposed ® Gaussian shape, longer snapback-time

•Improved b2 drift amplitudes ® exponential b2 fit?

•saturation of flat-top duration effect on drift amplitude ® foundation for elimination of pre-cycle

•a1 issue - progress on model for a1 in dipoles

•a1/b1 drift: first evidence found

main field drift: first evidence found

•re-shimming demonstration experiment

re-rolling experiment started

•magnetic measurement hardware for reference magnet system started